

# FACILITY COMPLIANCE AUDIT REPORT

# Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: Carteret
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		NOTIFICATION NO.: N0190
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

**Date of Audit:** 15 February 2011

#### **FACILITY NAME AND ADDRESS:**

Miller Farm LCID Landfill Miller Farm Road Morehead City, NC 28557

**GPS COORDINATES**: N: 34.74673 E: 76.79952

### **FACILITY CONTACT NAME AND PHONE NUMBER:**

Billy Miller 252.726.9429

### **FACILITY CONTACT ADDRESS:**

Miller Construction & Landscaping 205 Miller Farm Road Morehead City, NC 28557

### **AUDIT PARTICIPANTS**:

Billy Miller; Miller Construction & Landscaping Ray Williams; DENR-Solid Waste

## **STATUS OF PERMIT:**

Notified LCID

### **PURPOSE OF AUDIT:**

Comprehensive

### **NOTICE OF VIOLATION(S):**

None; please see AREAS OF CONCERN AND COMMENTS section below.

### **STATUS OF PAST NOTED VIOLATIONS:**

None applicable

### **AREAS OF CONCERN AND COMMENTS**:

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is secured by a locked gate at the facility entrance and has controlled access for safety.
- 3) The access road to the facility is being managed properly at this time.
- 4) Proper signage is posted at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 5) Receptacles are maintained at the site for the removal of unpermitted wastes.
- 6) No off-site erosion was noted during this audit.

#### FACILITY COMPLIANCE AUDIT REPORT

## Division of Waste Management Solid Waste Section

N0190, 021511

Page 2 of 3

- 7) The waste type being disposed is LCID waste only; no unacceptable waste streams were noted during this audit.
- 8) The active working area is approaching one acre in size. \*Please ensure that the active working face is covered monthly or when it approaches one acre in size, whichever occurs first.
- 9) All the landfill sideslopes have not been covered adequately and graded to promote positive drainage of surface waters.\*Within thirty days of receipt of this audit report, please compact, cover and grade all sideslopes at a slope of not greater that 3:1. All covered and graded areas should then be seeded and mulched to establish a groundcover suitable to prevent erosion of the landfill cap.
- 10) \*Please install permanent markers around the perimeter of the landfill to identify the landfill footprint boundaries.
- 11) Soil has been stockpiled for use as cover adjacent to the landfill access ramp.
- 12) This facility is recorded with the Carteret County Register of Deeds at: Book 666; Page 132.
- 13) Digital photographs were taken during this audit; please see photographs attached below.
- 14) \*Corrective actions are needed as a result of this Audit.

Please contact me if you have any questions or concerns regarding this audit report.

Ray Williams

cc:

Ray Williams; Environmental Senior Specialist: (signature) Phone: 910.796.7342 E-mail: ray.williams@ncdenr.gov

### Regional Representative

Delivered on: 21 February 2011 by		Hand delivery	X	US Mail		Certified No. [_]
-----------------------------------	--	---------------	---	---------	--	-------------------

Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov Donald Herndon; Chief Compliance Officer/SWS: donald.herndon@ncdenr.gov Wendy McNeil; FRO Administrative Services/SWS: wendy.mcneil@ncdenr.gov

C: /2010/Carteret/Notifications/N0190/Audits/N0190, 021511

# FACILITY COMPLIANCE AUDIT REPORT

# Division of Waste Management Solid Waste Section

N0190, 021511

Page 3 of 3



Proper signage posted at the landfill entrance

Landfill access; note signage, trash receptacles, and soil stockpile



Sideslope needing cover

Working area needing cover and grading